

Date: Thursday, 25/10/2007 12:41:00 PM
 User: Linda Lacelle

Process Sheet

Customer	: CC-DAR01 Dart Aerospace Ltd.			Drawing Name	: G10610-2		
Job Number	: 35391			Part Number	: D36431		
Estimate Number	: 10804			Drawing Number	: RE-IDENTIFY		
P.O. Number	:			Project Number	:		
This Issue	: 25/10/2007	S.O. No.	:	Drawing Revision	:		
Prsht Rev.	: NC			Material	:		
First Issue	: / /	Type	: SMALL /MED FAB	Due Date	: 01/11/2007 Qty: 12 Um: Each		
Previous Run	: 35390			Comment	:		
Written By	:			<i>[Signature]</i>			
Checked & Approved By	:			<i>[Signature]</i>			
Comment	:			<i>[Signature]</i>			

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
1.0	PACKAGING 1	PACKAGING RESOURCE #1 <i>C40711102 12</i>
2.0	G106102	Stiffener <i>C40711102 12</i>
3.0	SMALL FAB 1	SMALL & MEDIUM FAB RESOURCE 1 <i>Save parts less time to remove on waterjet</i> <i>✓ 07/11/02 21</i>
4.0	QC5	INSPECT WORK TO CURRENT STEP <i>✓ 07/11/02 21</i>
5.0	PACKAGING 1	PACKAGING RESOURCE #1 <i>✓ 07/11/02 21</i>

Date: Thursday, 25/10/2007 12:41:00 PM
User: Linda Lacelle

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: G10610-2

Job Number: 35391

Part Number: D36431

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0 QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion




✓ - 2008/2/21

0

U

8 7 6 5 4 3 2 1



8 7 6 5 4 3 2 1